

## **Yealink Flagship Smart Video Phone VP59 Release Notes of Version 283**

### **Table of Contents**

<b>Yealink Flagship Smart Video Phone VP59 Release Notes of Version 283.....</b>	<b>1</b>
<b>Yealink Flagship Smart Video Phone VP59 Release Notes of Version 91.283.0.40.....</b>	<b>2</b>
1. Introduction.....	2
2. New Features.....	2
3. Optimization.....	2
4. Bug Fixes.....	2
<b>Yealink Flagship Smart Video Phone VP59 Release Notes of Version 91.283.0.30.....</b>	<b>3</b>
1. Introduction.....	3
2. New Features.....	3
3. Optimization.....	3
4. Bug Fixes.....	3

## Yealink Flagship Smart Video Phone VP59 Release

### Notes of Version 91.283.0.40

#### 1. Introduction

- Firmware Version:  
VP59: 91.283.0.30 upgrades to 91.283.0.40
- Applicable Models: VP59
- Release Date: Sept 18<sup>th</sup>, 2019.

#### 2. New Features

None

#### 3. Optimization

None

#### 4. Bug Fixes

1. Fixed an issue that there will be a Web security risk caused by Command Injection, Path-Traversal, Cross-Site-Request-Forgery (CRFS), etc.
2. Fixed an issue that the invalid characters in the value of rsakey parameter will result in Web service crashing.

## Yealink Flagship Smart Video Phone VP59 Release

### Notes of Version 91.283.0.30

#### 1. Introduction

- Firmware Version:  
VP59: 91.283.0.20 upgrades to 91.283.0.30
- Applicable Models: VP59
- Release Date: Jun 11<sup>th</sup>, 2019.

#### 2. New Features

None

#### 3. Optimization

None

#### 4. Bug Fixes

1. Fixed a probabilistic issue that there may be a logic error on dialing screen.